## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.







FIG. 1




F16.2




F16. 3




F16.4



F16.5




F16.6




F14.8

A APC Back-UPS HS 500 - Microsoft Internet Explorer

E Status Page





About Rago	
12-05-2003	Bate y replacement date (mm-dd-yyyy):
10-21-2003	UPS date of manufacture (mm-dd-yyyy):
	Web funwere resision:
9	Firmware texision;
AB0343147115	Serial number:
APC Back-UPS HS 500	Model:
	Technical Parameters
00.C0.B7.25.0D.4E	MAC Address:
159.215.32.180	IP Address:
	Network Parameters
APC Back-UPS HS 5  Maintenance  Logoff	Sintus Configuration
	Adgess (से) http://189.215.32.160)
eda Ø   Ø ⋅ P ₪ ⋅ L ⋅ S	O Beack - O - N O O O Search K Favorter of Meda & S & B W - U 3
	File Ects View Feworkes Tocks Help

F16, 11

S interret




FIG. 12




FIG. 13